

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




FIG. 1




FIG. 2




FIG. 3



FIG. 4A





FIG. 4B



*FIG. 5*








FIG. 6





condition	MI	70 °C
TMPO	0.033	cc/min
N2	3.0	l/min



## RISE RESPONSE





FIG. 7

# FIG. 8



Adhesion conditions of TMPO decomposition / part enclosed by O  
matter in the valve sheet





FIG. 9




FIG. 10






FIG. II

